

Exova Warringtonfire Aus Pty Ltd  
 Unit 2, 409-411 Hammond Road  
 Dandenong, Victoria 3175  
 Australia

T: +61 (0)3 9767 1066  
 F: +61 (0)3 9767 1001  
 E: market.pacific@exova.com  
 W: www.exova.com



Postal Address:  
 PO Box 4282  
 Dandenong South, Victoria 3164  
 Australia

Testing. Advising. Assuring.

|                                       |                                     |                    |
|---------------------------------------|-------------------------------------|--------------------|
| <b>EWFA CERTIFICATE OF ASSESSMENT</b> | <b>CERTIFICATE No: SFC 26247-01</b> | <b>Page 1 of 1</b> |
|---------------------------------------|-------------------------------------|--------------------|

| Report Sponsor                                                      | Certificate Issue Date |
|---------------------------------------------------------------------|------------------------|
| ModWood Technologies Pty Ltd<br>5 Jessica Road<br>Campbellfield VIC | 25/06/2013             |

**Introduction**

This certificate confirms the element of construction described below was assessed by this laboratory on behalf of the test sponsor in accordance with the stated test standard and achieved the results stated below. Refer to the referenced assessment report for more information.

| Referenced Report | Report Issue Date | Test Standard    |
|-------------------|-------------------|------------------|
| EWFA 26247-01     | 25/06/2013        | AS1530.8.1-2007. |

| Description of Product       |                                                                                                                                                                    |                |
|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|
| Product Name                 | Assessed Construction                                                                                                                                              | Rating         |
| ModWood Flame Shield Decking | Decking Size; 137mm wide × 23mm thick<br>Decking Gap; Nominally 4mm<br>Subfloor Framing arrangement; Unenclosed<br>Framing Species; Various (Refer to full report) | <b>BAL A40</b> |

**Notes**

**THIS CERTIFICATE IS PROVIDED FOR GENERAL INFORMATION ONLY AND DOES NOT COMPLY WITH THE REGULATORY REQUIREMENTS FOR EVIDENCE OF COMPLIANCE.**

Reference should be made to the relevant assessment report to determine the applicability of the test result to a proposed installation and for a full description of the tested construction.

The results of these fire tests may be used to assess fire hazard, but it should be recognised that a single test method will not provide a full assessment of fire hazard under all conditions.

|                          |                                                                                          |             |                   |
|--------------------------|------------------------------------------------------------------------------------------|-------------|-------------------|
| <b>TESTING AUTHORITY</b> | Exova Warringtonfire Aus Pty Ltd                                                         |             |                   |
| <b>Address</b>           | PO Box 4282 DANDENONG SOUTH VIC 3164<br>Unit 2, 409-411 Hammond Road, DANDENONG VIC 3175 |             |                   |
| <b>Phone / Fax</b>       | +61 (0) 3 9767 1000 / +61 (0) 3 9767 1001                                                |             |                   |
| <b>ABN</b>               | 81 050 241 524                                                                           |             |                   |
| <b>Email / Home Page</b> | <a href="http://www.exova.com">www.exova.com</a>                                         |             |                   |
| <b>Authorisation</b>     | Prepared By:                                                                             | Revised by: | Reviewed By:      |
|                          | <br>K. G. Nicholls                                                                       | <br>S. Hu   | <br>K.G. Nicholls |